



Figure 1




Figure 2



Figure 3



Figure 4




Figure 5




Figure 6




Figure 7




Fig. 8A





Fig. 8B

2022071.012202






Figure 10




Figure 11

20221011.012202





Fig. 12






Fig. 14






Fig. 15






Fig. 18




Fig. 19

Fig. 20

Copper coil on polyimide (top)

242

244

250

Adhesive layer with hole

248

Copper coil on polyimide (bottom)

254

252

Detailed description: This exploded perspective view shows three components. The top component (242) is a dark, rectangular layer with a spiral copper coil (244) on its surface. The middle component (248) is a lighter, rectangular adhesive layer with a central circular hole (250). The bottom component (252) is another dark, rectangular layer with a spiral copper coil (254) on its surface. A large curly bracket on the left side groups all three components together. Handwritten labels with leader lines identify each part: 'Copper coil on polyimide (top)' for 242, 'Adhesive layer with hole' for 248, and 'Copper coil on polyimide (bottom)' for 252. The coil patterns are labeled 244 and 254, and the hole is labeled 250.




Figure 21

Fig. 22

Pressure sensitive capacitor 256





Fig. 23






Figure 25




Fig. 24







Fig. 26

10054671.012202






Figure 31




Figure 30




Figure 32




Figure 33




Figure 34

20231071.012202

202207291500T 10054671.013202




Fig. 35

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.